

# Plemons Options



## ASSEMBLY 2000302 L/R TRAY FORM ANTI WIPE KWIK CHANGE

ITEM	PART NO.	DESCRIPTION	QTY.
1	0014708R/L	SHOE, TRAY KC	2/2
2	0084700R/L	BLOCK, COMPRESSION SHOE ADJ	REF
3	0034100	BAR, CLAMP	4
4	0054204R/L	MOUNT, COMPRESSION BEARING	2/2
5	0018802R/L	PLOW, FLANGE FORMING	2/2
6	0016901	PAWL, TRAY STRIPPER	4
7	0019103	SHOE, TRAY FORMING GUIDE	4
8	0031501	PLATE, AUXILIARY COMPRESSION	4
9	0084500	CAP, TOP COMPRESSION SUPP	4
10	0084600	SPACER, TOP COMPRESSION	8
11	0031601	SPACER	4
100	8010500	3/8-16 HEX HD CAP SCR X 2 1/4	8
101	8024500	3/8-16 STD HEX NUT	8
102	8036700	5/16 STD LOCK WASHER	16
103	8008300	5/16-18 HEX HD CAP SCR X 1	12
104	8010400	3/8-16 HEX HD CAP SCR X 2	16
105	8035900	3/8 SAE FLT WASHER	8
106	1200800	SPRING	8
107	8009900	3/8-16 HEX HD CAP SCR X 3/4	8
108	8024900	3/8-16 HALF HEX NUT	8
109	0501101	FLANGE BEARING	4
110	0207400	BUSHING	4
111	0206000	BUSHING	4
112	0200900	BUSHING	4
113	0207100	BUSHING	4
114	8007300	1/4-20 HEX HD CAP SCR X 1 3/4	4
115	8000500	1/4-20 BUTTON HD SCKT SCR X 1	4
116	8036600	1/4 STD LOCK WASHER	8
117	8032100	1/4-20 SCKT HD CAP SCR X 2 1/4	4
118	1201600	SPRING	4
119	8025500	1/4-20 FIBER LOCK NUT	8
120	8007400	1/4-20 HEX HD CAP SCR X 2	4
121	8031600	1/4-20 SCKT HD CAP SCR X 1	4
122	0201200	BUSHING	8
123	8036800	3/8 STD LOCK WASHER	24
124	1501100	WASHER	4
125	8007100	1/4-20 HEX HD CAP SCR X 1 1/4	4

