

Plemons Options



ASSEMBLY 2000301 R/L TRAY FORM ANTI WIPE ASSEMBLY

ITEM	PART NO.	DESCRIPTION	QTY.
1	0014701L/R	SHOE, TRAY FORMING	2/2
2	0018802L/R	SHOE, TRAY FLANGE FORMING	2/2
3	0019103	SHOE, TRAY FORMING GUIDE	4
4	0031504	PLATE, TRAY COMPRESSION EXT.	4
5	0034100	BAR, SHOE BOX FORMING CLAMP	4
6	0200900	SPACER, TRAY COMP. PLATE	4
7	0207400	SPACER, TRAY FORM SHOE PLOW	4
8	0207100	SPACER, OUTSIDE FLAP FORMING	8
9	0054201	MOUNT, COMP. BEARING	4
10	0206000	SPACER	4
11	1501100	WASHER	4
12	0016901	PAWL, TRAY STRIPPER	4
100	0501101	BEARING	4
101	1200800	SPRING	8
102	8007300	1/4 NC X 1 3/4 HEX HD SCR	4
103	8032100	1/4 NC X 2 1/4 SKT HD ALLEN SCR	4
104	8007500	1/4 NC X 2 1/4 HEX HD SCR	4
105	8008300	5/16 NC X 1 HEX HD SCR	12
106	8008400	5/16 NC X 1 1/4 HEX HD SCR	4
107	8009900	3/8 NC X 3/4 HEX HD SCR	8
108	8010300	3/8 NC X 1 3/4 HEX HD SCR	8
109	8035900	3/8 FLAT WASHER	8
110	8036800	3/8 LOCK WASHER	8
111	8024900	3/8 NC HALF NUT	8
112	8036700	5/16 STD LOCK WASHER	8
113	8036600	1/4 STD LOCK WASHER	8
114	8007300	1/4 NC X 1 3/4 HEX HD SCR	4
115	8000500	1/4 X 1.0 NC BUTTON HD SCR	4
116	1201600	SPRING	4
117	8025500	1/4 NC FIBER LOCK NUT	8

