

Plemons Options



ASSEMBLY 2000303 L/R TRAY FORM ANTI WIPE GROOVEVY

ITEM	PART NO.	DESCRIPTION	QTY.
1	0010703	SPREADER, FRAME (SB)	REF
*	0010705	SPREADER, FRAME (WB)	REF
2	0014704L/R	SHOE, TRAY FORMING	2/2
3	0018804L/R	SHOE, TRAY FLANGE FORMING	2/2
4	0019103	SHOE, TRAY FORMING GUIDE	4
5	0021600	PLATE, GUIDE SUPPORT	REF.
6	0022202	SPACER, BAR SUPPORT	REF.
7	0022302	SUPPORT GUIDE BAR	REF.
8	0022605	ROD, TRAY FORM COMPRESSION	2
9	0031504	PLATE, TRAY COMPRESSION EXT.	4
10	0034100	BAR, SHOE BOX FORMING CLAMP	4
11	0200900	SPACER, TRAY COMP. PLATE	4
12	0207400	SPACER, TRAY FORM SHOE PLOW	4
13	0207100	SPACER, OUTSIDE FLAP FORMING	8
14	0054201	MOUNT, COMP. BEARING	4
15	0501101	BEARING	4
16	1200800	SPRING	8
17	8007300	1/4 NC X 1 3/4 HEX HD SCR	4
18	8032100	1/4 NC X 2 1/4 SKT HD ALLEN SCR	4
19	8007500	1/4 NC X 2 1/4 HEX HD SCR	4
20	8008300	5/16 NC X 1 HEX HD SCR	16
21	0206000	SPACER	4
22	8008400	5/16 NC X 1 1/4 HEX HD SCR	4
23	8008500	5/16 NC X 1 1/2 HEX HD SCR	8
24	8008700	5/16 NC X 2 HEX HD SCR	4
25	8009900	3/8 NC X 3/4 HEX HD SCR	8
26	8010300	3/8 NC X 1 3/4 HEX HD SCR	8
27	8035900	3/8 FLAT WASHER	8
28	8036800	3/8 LOCK WASHER	8
29	8024900	3/8 NC HALF NUT	8
30	8024400	5/16 NC NUT	4
31	8036700	5/16 STD LOCK WASHER	20
32	8036600	1/4 STD LOCK WASHER	8
33	1501100	WASHER	4
34	0016901	PAWL, TRAY STRIPPER	4
35	8007300	1/4 NC X 1 3/4 HEX HD SCR	4
36	8000500	1/4 X 1.0 NC BUTTON HD SCR	4
37	1201600	SPRING	4
38	8025500	1/4 NC FIBER LOCK NUT	8

* = Wide Base

